

BUILDING SAFETY CERTIFICATE

No. Bldg/FITT/2026/1656/19

Dated:19-08-2026

It is certified that the existing building MGM International School, Kilimanoor at Porunthamon, Pulimath ,Kilimanoor,Trivandrum, is having block (s) /Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Bldg No 5,56 G+2= 03 34.40x15x3.0 0 RCC Roof 34.40x15.00x3.00 34.40x3.00x3.00	Bldg No 5/50 G+1=02 28.30x15.00x3.00 28.30x15.00x3.00 00	Bldg No 5/158 G+2=03 29.65x17.36x3.00 29.65x17.36x3.00 29.65x17.36x3.00	Bldg NO 5/189 G+2=03 28.31x16.25x3.10, RCC Roof,28.31x16.25x3.10, RCC Roof,28.31x16.25x3.10, RCC Roof		


The building is owned/occupied by MGM International school , Kilimanoor at Porunthamon, pulimath ,Kilimanoor,Trivandrum have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Building Inspector and **Biju Kumar** Assistant Engineer Pulimath Gramapanchayathu Kilimanoor on 19 Aug 2026 in the presence of Manager/Principal MGM International school , Kilimanoor and that the building/premises is fit for occupancy for running school with effect from **one year** for a period of one years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Foundation and Basement	Fit/Yes
2. Super Structure	Fit/Yes
3. Door & Window	Fit/Yes
4. Wood Work	Fit/Yes
5. Roof	RCC/Sheet
6. Floor	Tiles & Granite
7. Miscellaneous (Crack etc)	Nil

Wither the Structure is sound or not for conducting Classes -Building is structurally sound for conducting Classes under normal wind and whether condition

Issued on 19-08-2026 at Assistant Engineer Office Pulimath Gramapanchayathu Kilimanoor

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



(Handwritten Signature)
Assistant Engineer
LSGD, Section
Pulimath Grama Panchayat