Fitness Certificate of School Building

To be filled by the Inspecting Officer (Asst. Engineer)

1	Name of the officer	_ Smt.Deepa.D.R
2	Name of School	_ VIDYA MOUNT PUBLIC SCHOOL
3 4	Location with name of Edn.Dist./Sub.Dist. Classification of building and size	Mangalapuram, Thiruvanathapuram Plinth area Block I. G.F -503.26 m2(RCC) Block I. F.F -503.26 m2 (RCC) Block II G.F -506.09m2 (RCC)
	i Permannent (Single or Multi storeyed) ii Semi permanent ii Temporary shed	_ Multistoried _
5 6	Period of which the certificate is issued Nature of defect if any a. Foundation and basement b. Superstructure c. Doors & windows d. Roof e. Flooring f. Miscellaneous (cracks etc.)	
7	Any major defects noticed which will render the building unsafe if any manner. Whether maintenance work have been done	
9	properly. Whether the structure is sound or not for conducting classes. Note:-	YesThe structure is sound under normal wind & weathercondition.

- ¹ The suitability of the structure should be examined also with reference to location attitude intensity of wind, exposure to flood etc.
- ² Any additional observations if deemed for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 20.01.2022 and found to be fit to conduct classes for the period 2021-2022 for the reason stated above.

Place - Mangalapuram
Date - 21/01/2022



Signature Designation

ASSISTANT ENGINEER
Local Salt Govt. (PV.)