

TO BE FILLED UP BY THE INSPECTING OFFICER (ASSISTANT ENGINEER)

FITNESS CERTIFICATE

1. Name of Officer - Murali. A., Assistant Engineer,,
LSGD Section, Vembayam GP.
2. Name of School - MGM TRINITY SCHOOL,
3. Location with Educational District /Sub. Dis - Vettinadu, Thiruvananthapuram.
4. Classification of buildings as specified in Column
For the application for fitness certificate and size - Permanent Multistored RCC building
GF 31.0x14.80x3.60
40.60x14.80x3.60
51.20x14.80x3.60
FF 40.60x14.80x3.60
51.20x14.80x3.60
SF 24.10x14.80x3.60
5. Period for which Certificate is issued - 2023-2024
6. Nature of defect if any
(a) Foundation and basement
(b) Super structure
(c) Doors and windows
(d) Wood work and wrought and put up
(e) Roof
(f) Flooring
(g) Miscellaneous(cracks etc..) } Nill
7. Any major defects noted which will renders the
buildings Unsafe in any manner - Nill
8. Whether the structure is sound or not for conducting
Classes - Based on the structural stability
certificate Dated 06/06/2022 (Issued by
Sri. Anseer. B., ME (Structural)
Engineer A, Licence No. E-4218/14/EA-
830/KLM, Department of Urban Affairs,
Government of Kerala.
9. Whether maintenance works have been done properly - Yes

Note:- 1. The stability of the structure should be examined also with reference to location
altitude intensity Of wind , exposure to flood etc.

2. Any additional observations it deemed necessary for the certificate may be furnished
separately with the certificate

Certified that the school was inspected by me on 20/06/23..... and found to
be fit/unfit to Conduct classes for the period2023 - 2024..... for the reasons stated
above.


Place: Vembayam

Date: 21/06/23



Signature

Designation



[Handwritten signature]