

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms 20/70/PWD Dt. 23-01-1970)

- Name of the Officer: Dr. Mumtaz, M
  - Name of the School: MGM Vidya mount Public School
  - Location with name of Education District/ Sub. District: Ekadavilakum, Mangalapuram  
Thiruvananthapuram
  - Classification of Building as specified in column 4 of the application for fitness certificate and size: Multi storied  
Plinth area - Block I - G.F - 503.26m<sup>2</sup> (RCC)  
Block II - F.F - 503.26m<sup>2</sup> (RCC)  
Block III - G.F - 506.09m<sup>2</sup> (RCC)
  - Period for which the certificate is issued: 2023-24
  - Nature of defects, if any:
    - Foundation and basement
    - Superstructure
    - Doors and Windows
    - Wood work wrought and put up
    - Roof
    - Flooring
    - Miscellaneous (Cracks, etc.)

Nil
  - Any major defects noticed which will render the building unsafe in any manner
  - Whether maintenance works have been done properly: Yes
  - Whether the structure is sound or not for conducting classes: The structure is sound under normal wind and weather conditions
- Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 25/05/2023 and  
found to be fit / unfit to conduct classes, for the period 2023-24 for the  
reasons stated above.

Place: Mangalapuram  
Date: 25/05/2023

(Seal)

Assistant Engineer

MANGALAPURAM MUNICIPAL CORPORATION  
MANGALAPURAM, MUFUKKUNJUZHA P.O.  
THIRUVANANTHAPURAM - 695 302

*self attested*