FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

	(No. 0.0. IVIS. 20110)		
Na	me of the School : Poppe	udi	valley public school, chasupara
1.	Name of the Officer	55	Assistant Engineer office of the Assistant Engineer, LIDAEW Section Tholikkod grams panchagalt Attingal, Palode
2.	Location		Attingal, palade
3.	Period for which the certificate is issued	:	0023-24
4.	Types of building	1:	permanent. 1. Buildingno. 1. GF 4.75 X 13.7 X 3.6 m
5.	Nature of defect if any		NIL FF45F (8-65X13-7X3-6m)
	a) Foundation and basement	:	GE, FF \$3F-(31.8 x 8.60 x 3.60
	b) Superstructure	:	7
	c) Doors and windows	:	Library GF - 13.5x12.35x3
	d) Wood work wrought and put up		FF-13:5x7.20x3.60
	e) Roof		Temperory open auditorium
	f) Flooring		\$3.40x11.00 m
	g) Miscellaneous (Cracks if any)	:	
6.	Any Major defects notices which will render the building unsafe in any manner	:	NIL
7.	Whether maintenance works have been done properly	:	Yes
8.	Whether the structure is sound or not for conducting classes	;	conder normal coind and courtes conditions.
Note	e:- 1. The stability of the structure should altitude intensity of wind exposure or	be floor	examined also with reference to location

CERTIFICATE

2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the School was inspected by me on20-6-23			
and found to be fit / unfit to conduct classes for the period 2023-24			
for the reason stated above.			
Place: Tholikkod 199 969: Nid (Sea!) Assistand Engineer Place: 23.06.123 Assistand Engineer			